


Curvas 90° para soldar


T618-90



Nº CODIGO	Ø Exterior Caño
T618-90-04	1/4"
T618-90-05	5/16"
T618-90-06	3/8"
T618-90-08	1/2"
T618-90-10	5/8"
T618-90-14	7/8"
T618-90-16	1"
T618-90-20	1 1/4"
T618-90-24	1 1/2"
T618-90-32	2"

Curvas 45° para soldar

T618-45



Nº CODIGO	Ø Exterior Caño
T618-45-04	1/4"
T618-45-05	5/16"
T618-45-06	3/8"
T618-45-08	1/2"
T618-45-10	5/8"
T618-45-14	7/8"
T618-45-16	1"
T618-45-20	1 1/4"
T618-45-24	1 1/2"
T618-45-32	2"

"Poberaj SA se reserva el derecho de modificar las características y medidas de sus productos sin previo aviso".

PENSAMOS EN SEGURIDAD
TRAZABILIDAD

